

Salt Lake County  
**2023 Year-End Decision Package Summary**  
 by Linked Form ID

**Form ID:** 30309

**Name:** Repair Flood Damage at South Mountain GC

**Request Description:** This request sets up a new capital project to remedy damage caused by flooding at South Mountain Golf Course on August 4, 2023, and September 4, 2023. Various tee areas, fairways, cart paths, and hills sustained damage. All of the course's 62 sand bunkers were washed out. The project budget will provide engineering design work and construction to repair drainage, replace washed-out sand, reshape damaged landscape, and ensure course safety and playability. This is a one-time request from fund balance.

Current Stage	Type	Council Approval	Council Approval Date
5007 - Mayor	New Capital Project	No	

Fund, Org, SubDept, Project/Program, Account	Revenues	Expenses	Transfer In and OFS	Transfer Out and OFU	Balance Sheet	Net Change to Fund Balance	FTE
<b>710 - Golf Courses Fund</b>							
<b>38209900 - Golf Capital Projects</b>							
<b>3820990000 - Golf Capital Projects</b>							
<b>PARG23SMGC Repairs @ South Mountain Golf Course</b>							
607010 - Maintenance - Grounds	0	1,000,000	0	0	0	(1,000,000)	0.00
<b>Total Golf Capital Projects</b>	0	1,000,000	0	0	0	(1,000,000)	0.00
<b>Total Golf Courses Fund</b>	0	1,000,000	0	0	0	(1,000,000)	0.00

Future Year Adjustments	Revenues	Expenses	Transfer In and OFS	Transfer Out and OFU	Balance Sheet	Net Change to Fund Balance	FTE
<b>710 - Golf Courses Fund</b>							
<b>38209900 - Golf Capital Projects</b>							
<b>3820990000 - Golf Capital Projects</b>							
<b>PARG23SMGC Repairs @ South Mountain Golf Course</b>							
607010 - Maintenance - Grounds	0	(1,000,000)	0	0	0	1,000,000	0.00
<b>Total Golf Capital Projects</b>	0	(1,000,000)	0	0	0	1,000,000	0.00
<b>Total Golf Courses Fund</b>	0	(1,000,000)	0	0	0	1,000,000	0.00

<b>Budget Year - Grand Total</b>	0	1,000,000	0	0	0	(1,000,000)	0.00
<b>Future Year Adjustments - Grand Total</b>	0	(1,000,000)	0	0	0	1,000,000	0.00

Form ID	Attachments
30309	30309_1.12.01YE-Repair Flood Damage at South Mountain GC 230929_20230929T170425.pdf

