2022 Unincorporated Capitol Projects Requests

Ranking	Project Description	Location of Project	Engineering Comments	Cost Estimate
1*	8475 S Sidewalk; 700 E to 871 E	Unincorporated Island	Design and construction cost (estimated)	\$208,077
	8430 S Mesa Drive Sidewalk; north side of property	Sandy Hills CC	Design and construction cost (estimated) - additional cost if retaining wall is req'd	\$100,000
3*	3100 E Sidewalk; LC Road - Dimple Dell	Granite CC	Design and construction cost (estimated) - sidewalk on one side of roadway	\$250,000
4*	adding wood chip pathway	Granite CC - Dimple Dell Road update study and estimate adding wood chip pathway	Cost estimate to update study and provide recommendations	\$40,000
5	Driver Feedback Signs	Sandy Hills CC - 8425 South Street	Traffic Hazard index of 117, recommend feedback signs (set)	\$10,000
6	Driver Feedback Signs	Sandy Hills CC - Galaxie Dr.	Traffic Hazard index of 95, recommend feedback signs (set)	\$10,000
	A designated walk way or sidewalk at the entrance of Wasatch Resort road down to the widest part of the road.		Design and construction cost (estimated) -sidewalk on one side of roadway	\$350,000
			Total =	\$1,232,506

^{*} denotes project may be eligible for grant funding (safe route to school, transportation alternative plans, transportation and land use program)



2022 Engineering Capital Improvement Project Recommendations Unincorporated Salt Lake County

Priority 1 – 8475 S Sidewalk 700 E to 871 E

Unincorporated Island



- Design and construction estimate = \$208,077
- Community requested for SW on 8475 S (Vic's Rd) for Safe Route to Union MS
- Safe Route to School for East Sandy Elementary




Priority 2 — 8430 S and Mesa Drive Sandy Hills Community Council



Priority 3 - 3100 E Sidewalk LC Rd to Dimple Dell Rd Granite Community Council

Design and construction cost (estimated) = \$250,000 Design for sidewalk in Unincorporated sections of 3100 E from Little Cottonwood Rd to Dimple Dell Rd. Requested by Granite Elementary School on 3100 E No sidewalk on either side of road in sections and on Safe Route to School plan. Bell Banyon Ro

Priority 4 - Dimple Dell Rd Woodchip Path Granite Community Council



Priority 4 - Dimple Dell Rd Woodchip Path




Priority 5 - 8425 S Driver Feedback Signs

Sandy Hills Community Council

Install two driver feedback signs, cost estimate = \$10,000

 Traffic study indicates a hazard index of 117 on 8425S and driver feedback signs are recommended for traffic calming



Priority 6 - Galaxie Dr Driver Feedback Signs

Sandy Hills Community Council



Priority 7 - Wasatch Resort Rd Granite Community Council



Request for walkway or sidewalk from Wasatch Rd and SR210 intersection to widest part of road, one side of roadway

 Safety issue generated by people parking on SR210 and walking in road on Wasatch Resort Rd